



Electronic Unit Pumps and Injector Assemblies for MBE900 & MBE4000 Engines

Program Guide

2213800 • FOOE380939 35E



BOSCH

Robert Bosch LLC
2800 South 25th Avenue
Broadview, IL 60155
Phone 708-865-5200
www.boschautoparts.com

Printed in U.S.A. All rights reserved.

Electronic Unit Pumps

Bosch Part No.	Bosch Reman No.	OEM No.(s)
0 414 799 005	0 986 445 102	028 074 59 02
0 414 799 007	0 986 445 016	028 074 61 02, A 028 074 61 02
0 414 799 008	0 986 445 103	028 074 69 02, RA 028 074 69 02
0 414 799 009	0 986 445 110	005 070 96 01
0 414 799 010	0 986 445 056	005 070 62 01
0 414 799 011	0 986 445 007	006 070 30 01
0 414 799 012	0 986 445 017	028 074 86 02, RA 028 074 86 02
0 414 799 013	0 986 445 018	028 074 92 02
0 414 799 014	0 986 445 019	028 074 90 02
0 414 799 015	0 986 445 020	028 074 89 02
0 414 799 016	0 986 445 114	006 070 41 01
0 414 799 017	0 986 445 021	028 074 91 02, EA 028 074 91 02
0 414 799 019	0 986 445 023	028 074 96 02
0 414 799 020	0 986 445 024	028 074 95 02
0 414 799 021	0 986 445 025	028 074 94 02
0 414 799 022	0 986 445 026	029 074 12 02, RA 029 074 12 02
0 414 799 023	0 986 445 115	535 073 00 00/1
0 414 799 024	0 986 445 022	028 074 88 02, A 028 074 88 02, RA 028 074 88 02, 0 414 799 018

Injectors

Bosch Part No.	OEM No.(s)
0432191271	002 010 55 21
0432191277	006 017 21 21
0432191278	006 017 22 21, 004 017 65 21, 002 010 25 51, 005 017 77 21
0432191285	006 017 03 21
0432193467	006 017 39 21
0432193475	006 017 29 21
0432193476	006 017 30 21, RA 002 010 36 51
0432193477	006 017 31 21
0432191262	006 017 44 21
0432191268	006 017 50 21
0432191269	006 017 51 21
0432191259	006 017 52 21, 002 010 51 51
0432191270	006 017 52 21

On Highway Applications

Make/Model	Model Year
FREIGHTLINER	
B2 Bus Chassis	2005-09
Cascadia 125	2008-09
Century CST112	2001-04
Century CST120	2001-09
Classic 120	2004-09
Columbia 112	2003-09
Columbia 120	2001-09
FB 65	2002-06
FL112	2002-08
FL50	2001-04
FL5042S	2000-01
FL60	2001-04
FL6042S	1999-01
FL70	2001-04
FL7042S	1999-01
FL7042ST	1999-01
FL80	2001-05
FL8042S	2000-01
FL8042ST	2000-01
FL8064S	1999-01
FLD112	2004-07
FLD11242S	2000
FLD120	2001-06
FLD120 SD	2006-09
FLD12042SX	2000

Make/Model	Model Year
FREIGHTLINER (cont'd)	
FLD132	2007
Legacy FLD120	2008
M2 100	2002-06
M2 106	2002-09
M2 112	2003-09
MB Line	2006-07
MT45	2001-08
MT45 HEV	2005
MT55	2004-07
S2 106 Bus Chassis	2007-08
School Bus FS65	2001-08
Sport Chassis M2 106	2005-07
Sport Chassis M2 112	2005-09
Sport Chassis 112	2003-04
Sport Chassis	2001-03
XC Series - Raised Rail	2005-06
XC Series - Straight Rail	2007-08
STERLING	
A9500	2003-09
AT9500	2003-08
Acterra	2003-09
Acterra M6500	2003
Cargo SC7000	2006
Cargo SC8000	2006
L7500	2004-09

Make/Model	Model Year
STERLING (cont'd)	
L8500	2004-08
L9500	2003-09
LT7500	2005-06
LT8500	2004-07
LT9500	2003-09
LC Car Hauler	2005-09
M6500	2001-03
M7500	2001-03
M8500	2001-03
THOMAS	
SAF-T-LINER MVP	2003
SAF-T-LINER	2003
SAF-T-LINER HDX	2003-09
SAF-T-LINER MVP EF	2002-03
SAF-T-LINER MVP ER	2003
Transit Liner HDX	2004-09
Transit Liner MVP EF	2002-03
Transit Liner MVP ER	2003
UNIMOG	
3350	2003-06
3900	2003-06
WESTERN STAR	
4900	2003-05
4900FA	2003-09
4900SA	2003-09

Core Return Policy

- Bosch will only accept MBE900 and MBE4000 series electronic unit pumps

Warranty Terms

- 12 Months, unlimited mileage/hours

Warranty does not cover:

- Repairs/Damage due to accidents, misuse, storage damage, negligence, modifications, improper installation, and damage caused by installer.
- Non-genuine pumps/injectors that were not supplied by Bosch
- Pumps/Injectors damaged due to dirty or contaminated fuel
- Pumps/Injectors where the problem can not be confirmed (No Trouble Found).